

# Work Order ID 74848

**\*74848\***

Page 1

Saturday, October 22, 2011 10:52:26 AM

Item ID: D2066 Accept **\*N900040100\*** Setup Start **\*NS1\***  
 Revision ID: Stop **\*NS2\***  
 Item Name: Arm  
 Start Date: 10/12/2011 Start Qty: 1.00 **\*1\*** Cust Item ID:  
 Required Date: 10/13/2011 Req'd Qty: 1.00 **\*1\*** Customer: CU-DAR001  
 Reference: RMA RA111275 - RETURN

Approvals: Process Plan: MF Date: 11-10-22 Tooling: \_\_\_\_\_ Date: \_\_\_\_\_  
 QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_  
 Run Start **\*NR1\***  
 Stop **\*NR2\***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2066	Rev C								

100 QC5- Inspect part completeness to step on W/O 0.00

**\*100\***

QC

Quality Control

Memo

INSPECT RA 111275  
D2066 B 13807

UPON INSPECTION IT WAS DISCOVERED THAT TAB WAS BROKEN

SCRAP PART

110 0.00

**\*110\***

Small Fab

Small Fab

Memo

SCRAP PART

*Scrap*

*[Handwritten signatures and dates: 11/11/10]*

**Work Order ID 74848****\*74848\***

Page 2

Saturday, October 22, 2011 10:52:26 AM

Item ID: D2066

Accept

**\*N900040100\***Setup Start **\*NS1\***

Revision ID:

Stop **\*NS2\***

Item Name: Arm

Start Date: 10/12/2011 Start Qty: 1.00

**\*1\***

Cust Item ID:

Required Date: 10/13/2011 Req'd Qty: 1.00

**\*1\***

Customer: CU-DAR001

Reference: RMA RA111275

Approvals:

Process Plan: \_\_\_\_\_

Date: \_\_\_\_\_

Tooling: \_\_\_\_\_

Date: \_\_\_\_\_

Run Start **\*NR1\***

QC: \_\_\_\_\_

Date: \_\_\_\_\_

SPC (Y/N): \_\_\_\_\_

Date: \_\_\_\_\_

Stop **\*NR2\***Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run Hours

Tool ID

Tool #

Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

120

QC21- Final Inspection - Work Order Release

0.00


**\*120\***

QC

Memo

0.00

Quality Control

11/11/14 MF  
11-11-11